MARYLAND HISTORICAL TRUST DETERMINATION OF ELIGIBILITY FORM

NR Eligible:	yes	
	no	

Property Name: Evan Dorsey Millers House	Inventory Number: F-5-30
Address: 6904 New London Road	Historic district: X yes no
City: New London Zip Code: 20740	County: Frederick
USGS Quadrangle(s): Walkersville	
Property Owner: M. Marguerite Hopkins T	ax Account ID Number: 09-232346
Tax Map Parcel Number(s): 75 Tax Map Number	r:69
Project: FR396B21, MD 874C over Bens Branch Agency:	MD SHA
Agency Prepared By: MD SHA	
Preparer's Name: Rita Suffness	Date Prepared: 04/06/2004
Documentation is presented in: MHT Easement and Inventory Files, and SHA Pro Branch	oject Files: FR396B21, MD 874C over Bens
Preparer's Eligibility Recommendation: Eligibility recommended	Eligibility not recommended
Criteria: X A B C D Considerations: A B	CDEFG
Complete if the property is a contributing or non-contributing resource	to a NR district/property:
Name of the District/Property: New London Historic District	
Inventory Number: F-5-15 Eligible: yes	Listed: yes
Site wisit by MUT Staff	Data
Site visit by MHT Staff yes X no Name:,	Date:
Description of Property and Justification: (Please attatch map and photo) In the original MIHP form (1978) the house was documented as being in severe dis 1976 and subsequent abandonment and neglect. In 1994 Janet Davis revealed in her District (F-5-15) that the house had been constructed in two stages. The western se ruins in 1994, had been built by Evan Dorsey in 1804, possibly as a residence, store was built in the same year. All but one wall of this section had been demolished by east, a 1829 deed states that James Smith was then occupying the property. He built between 1830 and 1840. This section was also heavily deteriorated in 1994, with a irregularly spaced bays on the upper levels. The roof was almost completely destro dormer in the front slope of the south facing structure. Although a preservation easement to the Maryland Historical Trust in 1983 had bee in 1983, restoration did not start until the late 1990's. The integrity of the structure due to the use of modern materials, such as siding and new windows. No outbuildiform or the updated form for the New London Survey District form (1994).	repair, having suffered from a serious fire in a documentation of the New London Survey ction of the building, which was completely in cor cooper shop connected with his mill, which 1994. As to the stone two-story portion on the this section during his tenure, probably an exposed basement level on the south and two syed, with the remnant of a shed roof garrison on given by the owner, Dr. Christopher Kennedy has been compromised in the restored structure,
Description of Property and Justification: (Please attatch map and photo) In the original MIHP form (1978) the house was documented as being in severe dis 1976 and subsequent abandonment and neglect. In 1994 Janet Davis revealed in her District (F-5-15) that the house had been constructed in two stages. The western se ruins in 1994, had been built by Evan Dorsey in 1804, possibly as a residence, store was built in the same year. All but one wall of this section had been demolished by east, a 1829 deed states that James Smith was then occupying the property. He built between 1830 and 1840. This section was also heavily deteriorated in 1994, with a irregularly spaced bays on the upper levels. The roof was almost completely destrodormer in the front slope of the south facing structure. Although a preservation easement to the Maryland Historical Trust in 1983 had been in 1983, restoration did not start until the late 1990's. The integrity of the structure due to the use of modern materials, such as siding and new windows. No outbuildit	repair, having suffered from a serious fire in a documentation of the New London Survey ction of the building, which was completely in cor cooper shop connected with his mill, which 1994. As to the stone two-story portion on the this section during his tenure, probably an exposed basement level on the south and two syed, with the remnant of a shed roof garrison on given by the owner, Dr. Christopher Kennedy has been compromised in the restored structure,
Description of Property and Justification: (Please attatch map and photo) In the original MIHP form (1978) the house was documented as being in severe dis 1976 and subsequent abandonment and neglect. In 1994 Janet Davis revealed in her District (F-5-15) that the house had been constructed in two stages. The western se ruins in 1994, had been built by Evan Dorsey in 1804, possibly as a residence, store was built in the same year. All but one wall of this section had been demolished by east, a 1829 deed states that James Smith was then occupying the property. He built between 1830 and 1840. This section was also heavily deteriorated in 1994, with a irregularly spaced bays on the upper levels. The roof was almost completely destrodormer in the front slope of the south facing structure. Although a preservation easement to the Maryland Historical Trust in 1983 had been in 1983, restoration did not start until the late 1990's. The integrity of the structure due to the use of modern materials, such as siding and new windows. No outbuilding form or the updated form for the New London Survey District form (1994).	repair, having suffered from a serious fire in a documentation of the New London Survey ction of the building, which was completely in cor cooper shop connected with his mill, which 1994. As to the stone two-story portion on the this section during his tenure, probably an exposed basement level on the south and two syed, with the remnant of a shed roof garrison on given by the owner, Dr. Christopher Kennedy has been compromised in the restored structure,
Description of Property and Justification: (Please attatch map and photo) In the original MIHP form (1978) the house was documented as being in severe dis 1976 and subsequent abandonment and neglect. In 1994 Janet Davis revealed in her District (F-5-15) that the house had been constructed in two stages. The western se ruins in 1994, had been built by Evan Dorsey in 1804, possibly as a residence, store was built in the same year. All but one wall of this section had been demolished by east, a 1829 deed states that James Smith was then occupying the property. He built between 1830 and 1840. This section was also heavily deteriorated in 1994, with a irregularly spaced bays on the upper levels. The roof was almost completely destrodormer in the front slope of the south facing structure. Although a preservation easement to the Maryland Historical Trust in 1983 had been in 1983, restoration did not start until the late 1990's. The integrity of the structure due to the use of modern materials, such as siding and new windows. No outbuilding form or the updated form for the New London Survey District form (1994). MARYLAND HISTORICAL TRUST REVIEW Eligibility recommended	repair, having suffered from a serious fire in a documentation of the New London Survey ction of the building, which was completely in cor cooper shop connected with his mill, which 1994. As to the stone two-story portion on the this section during his tenure, probably an exposed basement level on the south and two syed, with the remnant of a shed roof garrison on given by the owner, Dr. Christopher Kennedy has been compromised in the restored structure,
Description of Property and Justification: (Please attatch map and photo) In the original MIHP form (1978) the house was documented as being in severe dis 1976 and subsequent abandonment and neglect. In 1994 Janet Davis revealed in her District (F-5-15) that the house had been constructed in two stages. The western se ruins in 1994, had been built by Evan Dorsey in 1804, possibly as a residence, store was built in the same year. All but one wall of this section had been demolished by east, a 1829 deed states that James Smith was then occupying the property. He built between 1830 and 1840. This section was also heavily deteriorated in 1994, with a irregularly spaced bays on the upper levels. The roof was almost completely destro dormer in the front slope of the south facing structure. Although a preservation easement to the Maryland Historical Trust in 1983 had bee in 1983, restoration did not start until the late 1990's. The integrity of the structure due to the use of modern materials, such as siding and new windows. No outbuildiform or the updated form for the New London Survey District form (1994). MARYLAND HISTORICAL TRUST REVIEW Eligibility recommended Eligibility not recommended Criteria: A B C D Considerations: A MHT Comments:	repair, having suffered from a serious fire in a documentation of the New London Survey ction of the building, which was completely in cor cooper shop connected with his mill, which 1994. As to the stone two-story portion on the this section during his tenure, probably an exposed basement level on the south and two syed, with the remnant of a shed roof garrison on given by the owner, Dr. Christopher Kennedy has been compromised in the restored structure, the ings were noted in either the original MIHP
Description of Property and Justification: (Please attatch map and photo) In the original MIHP form (1978) the house was documented as being in severe dis 1976 and subsequent abandonment and neglect. In 1994 Janet Davis revealed in her District (F-5-15) that the house had been constructed in two stages. The western see ruins in 1994, had been built by Evan Dorsey in 1804, possibly as a residence, store was built in the same year. All but one wall of this section had been demolished by east, a 1829 deed states that James Smith was then occupying the property. He built between 1830 and 1840. This section was also heavily deteriorated in 1994, with a irregularly spaced bays on the upper levels. The roof was almost completely destro dormer in the front slope of the south facing structure. Although a preservation easement to the Maryland Historical Trust in 1983 had bee in 1983, restoration did not start until the late 1990's. The integrity of the structure due to the use of modern materials, such as siding and new windows. No outbuildiform or the updated form for the New London Survey District form (1994). MARYLAND HISTORICAL TRUST REVIEW Eligibility recommended	repair, having suffered from a serious fire in a documentation of the New London Survey ction of the building, which was completely in a or cooper shop connected with his mill, which 1994. As to the stone two-story portion on the a this section during his tenure, probably an exposed basement level on the south and two byed, with the remnant of a shed roof garrison are given by the owner, Dr. Christopher Kennedy has been compromised in the restored structure, ings were noted in either the original MIHP
Description of Property and Justification: (Please attatch map and photo) In the original MIHP form (1978) the house was documented as being in severe dis 1976 and subsequent abandonment and neglect. In 1994 Janet Davis revealed in her District (F-5-15) that the house had been constructed in two stages. The western se ruins in 1994, had been built by Evan Dorsey in 1804, possibly as a residence, store was built in the same year. All but one wall of this section had been demolished by east, a 1829 deed states that James Smith was then occupying the property. He built between 1830 and 1840. This section was also heavily deteriorated in 1994, with a irregularly spaced bays on the upper levels. The roof was almost completely destro dormer in the front slope of the south facing structure. Although a preservation easement to the Maryland Historical Trust in 1983 had bee in 1983, restoration did not start until the late 1990's. The integrity of the structure due to the use of modern materials, such as siding and new windows. No outbuildiform or the updated form for the New London Survey District form (1994). MARYLAND HISTORICAL TRUST REVIEW Eligibility recommended Eligibility not recommended Criteria: A B C D Considerations: A MHT Comments:	repair, having suffered from a serious fire in a documentation of the New London Survey ction of the building, which was completely in a cor cooper shop connected with his mill, which 1994. As to the stone two-story portion on the a this section during his tenure, probably an exposed basement level on the south and two byed, with the remnant of a shed roof garrison are given by the owner, Dr. Christopher Kennedy has been compromised in the restored structure, angs were noted in either the original MIHP

200400308

Page 2

F-5-30

The house is immediately adjacent to the east abutment of Bridge No. 10043, which carries New London Road (MD 874C) over Bens Branch. The dwelling is composed of two sections: the original side-gable frame portion, reconstructed above the above-grade stone foundation (with a centered door and two windows to each side), and the later, two-story, side-gable, two-bay wide, taller stone addition located east of the 1804 part.

SIGNIFICANCE: Three mills were constructed on Ben's Branch by the late 18th century. The gristmill at New London was built by Evan Dorsey in 1804, and a sawmill a short while later. The town was established around Evan Dorsey's mill in 1804. The road from Libertytown to New Market and the town of New London first appear on a map in 1839 (Davis 1994). At about the same time two houses were built that were associated with the mills. The Hobbs-Lowe House was located west of Bens Branch, and the Evan Dorsey Miller's House was located on the east side, and north of the road. Later, east-west roads, Gas House Pike and Lime Plant Road, intersected the New London Road (MD 874C) in the center of town. The development of the town depended on the success of the copper mine, established in the 1830's, and the mills during the nineteenth century. By 1858 a number of houses, a post office and store, a blacksmith ship and a wheelwright shop appear on the map of New London. By this time, one of the houses and some land were sold off separately from the mill property. The gristmill and sawmill, and the Hobbs-Lowe House were owned by William Hobbs, who had married Susan Dorsey, daughter of Evan Dorsey. From 1861 to 1865 the mill and the house changed owners several times, being owned for a brief period by the New London Copper Mining Company. The mills, dwelling, pump and dairy were shown on the mine plat made shortly after the company acquired the mine.

In summary, the house is considered eligible for inclusion in the NRHP, despite the diminished condition that once characterized it, because of its association with the owners of the mills, no longer extant, that were located at the crossing of New London Road and Bens Branch. It was evaluated in accordance with criteria of the National Register of Historic Places. These criteria state that the quality of significance in American History, architecture, archeology, and culture is present in districts, sites, buildings, structures, and objects that possess integrity of location, design, setting, materials, workmanship, feeling, and association, and: that are associated with events that have made a significant contribution to the broad patterns of our history (Criterion A); or that are associated with the lives of persons significant in our past (Criterion B); or that embody the distinctive characteristics of a type, period, or method of construction that represent the work of a master, or that possess high artistic values, or that represent a significant and distinguishable entity whose components may lack individual distinction (Criterion C); or that have yielded, or may be able to yield, information important in prehistory or history" (Criterion D) (36 CFR 63, and National Register Bulletin Series No. 15).

The dwelling has been analyzed within the context of the Agricultural-Industrial Transition Period (1815-1870), the Industrial/Urban Dominance Period (1870-1930), and the Modern Era (1930-Present) within Frederick County. As an important remnant of the original mill village, despite its ruinous state some years ago, retains integrity of location, setting, feeling, and association, for its connection with events that have made a significant contribution to the broad patterns of our history (Criterion A). It retains the level of integrity necessary for listing on the National Register of Historic Places. Its associations with the broad patterns of Frederick County, Maryland or national history, has been retained despite its restoration. It is especially important that it retains an important visual link with the roadway on which it is located. In its present state, it displays diminished architectural distinction as a former millers house, but nonetheless meets the National Register criterion A thorough its association with the history of milling. In summary, it has significance under Criteria A for its associations with the broad patterns of American history and qualifies for listing in the National Register. Along its frontage it does not retain enough intact archeological materials and features to meet the requirements of Criterion D, although the remainder of the property has not been tested for archeological resources and thus its eligibility under Criterion D has not been determined. The results of the investigations of portions fronting MD 874C within the area of impact for the bridge replacement have been reported in the "Phase I and Phase II Archeological Investigation Report at Bridge No. 10043 over Bens Branch at MD 874."

MARYLAN	ND HISTO	ORICAL	TRUST	REVI	EW							
Eligibility r	ecommen	ded		Eli	gibility not recommen	nded						
Criteria:	A ments:	В .	C	D	Considerations:	A	В	C	D .	E	F	G
_	Review	er, Offic	e of Pres	servatio	on Services			Date			et.	
-	Revie	wer, Na	tional Re	egister	Program			Date				

NR-FI	IGIRII	ITY	REVIE	W FORM

F-5-30


Evan Dorsey Millers House


Page 3


F-5-30

BOUNDARY: The boundary is coterminous with the north, west and south bounds of tax parcel 75 (Map 69), and with the SHA right-of way along MD 874C, to form the eastern border, encompassing ca. 2 acres.

MARYLAND HISTORICAL T	RUST REVIE	EW							
Eligibility recommended	Elig	gibility not recommen	ded						
Criteria:AB	_CD	Considerations:	A	_В	C	D	E	F	G
MHT Comments:									
P : 000								-	
Reviewer, Office of	of Preservatio	n Services			Date				
Reviewer, Natio	nal Register I	Program			Date				









two Vorsey Millers House N m Corner Sufferen Nov 03

2



F-5-30 Evan Dorse, Pullen House SE Entravee dacide Suffre 1. D stale huy rdm? neg n/ M1-17 1/2

F-5-30 Evan Dorsey Millers House New London Private

C. 1780

The Evan Dorsey Millers House is a $2\frac{1}{2}$ story coursed rubble stone structure built in two parts. The west section is three bays wide with large stone quoins occupying each corner of the building.

The east section is a banked building, two bays wide and one room deep with a six panel entrance door located in a recessed paneled doorway. The entire structure is in very poor condition and is

deteriorating.

The Evan Dorsey Millers House is believed to have been built in the late eighteenth century by Evan Dorsey who inherited the Drummine tract from his fathe Basil Dorsey. By 1858 the mill and millers house had been acquired by William Hobbs. The mill continued to operate until 1889 when a flood on the Linganore Creek left the building inoperable.

F-5-30 1100305204

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

NAME			
HISTORIC Evan Dorsey Millers Ho	ouse		
AND/OR COMMON			
LOCATION			
STREET & NUMBER North side Gas House	e Pike	Sixth E.D.	9
New London	VICINITY OF	CONGRESSIONAL DISTRI	СТ
STATE		COUNTY	
CLASSIFICATION			
CATEGORY MISTRICT BUILDING(S) STRUCTURE SITE OBJECT CATEGORY PUBLIC PRIVATE BOTH PUBLIC ACQUISITION IN PROCESS BEING CONSIDERED	STATUS X-OCCUPIED _UNOCCUPIED _WORK IN PROGRESS ACCESSIBLE _YES: RESTRICTED _YES: UNRESTRICTED _NO	PRESI _AGRICULTURE _COMMERCIAL _EDUCATIONAL _ENTERTAINMENT _GOVERNMENT _INDUSTRIAL _MILITARY	ENT USE MUSEUMPARKPRIVATE RESIDESRELIGIOUSSCIENTIFICTRANSPORTATIOOTHER: Vacan
Thom as W. Coerr a STREET & NUMBER 811 North 24th Street	Terrores in t		
CITY. TOWN Philadelphia	VICINITY OF	STATE 197	ip code
LOCATION OF LEGAL DESCR	IPTION	Liber #:	
COURTHOUSE. REGISTRY OF DEEDS, ETC.		Folio #:	
STREET & NUMBER	363 S F V 57		
CITY, TOWN		STATE	
REPRESENTATION IN EXIST	ING SURVEYS		
TITLE			
DATE	FEDERAL	TATE COUNTY LOCAL	
	FEDERALS	TATECOUNTYLOCAL	

CONDITION

EXCELLENT

__EXCELLENT

_FAIR

__DETERIORATED
__RUINS
__UNEXPOSED

CHECK ONE

____NALTERED

CHECK ONE

ORIGINAL SITE

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Evan Dorsey Millers House is a $2\frac{1}{2}$ story coursed rubble stone structure built in two parts which faces south from the north side of Gas House Pike in the old settlement of New London.

The west section of the building is 3 bays wide, a replaced entrance door is locted in the second bay on both the first and second level. A single large stone lintel is located over the entrance on the seconf level. Double hung 6/6 windows occupied the remaining bays but all have been replaced except for the window in the first bay from the southeast corner on the second level.

A two story open porch once extended across the facade of this section of the building but it has been removed. Large stone quoins are located in each corner of the building. A massive stone chimney which is deteriarating at the top rises on the west gable end. The original roof and cornice have been removed and replaced by a plywood gable roof with wide dormer.

The east section of the building is a banked building, 2 bays wide and one room deep. The main entrance, a six panel door located in a recessed paneld doorway with wood lintel occupies the second bay from the southwest corner. A crude wood entrance porch recently added leads to the entrance. No windows remain in the bay openings on the first and second levels although earlier photographs indicate that the first level bay had a 9/6 window and 6/6 occupied the remaining bays on the second level with wood lintels.

The stones used in the construction of this section of the house are smaller and smoother with a finer joint than the west section. The replaced gable roof is attached to the structure by a replaced plain boxed cornice.

A single brick chimny straddles the east gable. The entire structure is in very poor condition and is deteriorating.

8 SIGNIFICANCE

SPECIFIC DAT	ES	BUILDER/ARCH	HITECT Evan Dorsev	
		_INVENTION		
1900-	COMMUNICATIONS	INDUSTRY	POLITICS/GOVERNMENT	_OTHER (SPECIFY)
<u>1800-1899</u>	A COMMERCE	_EXPLORATION/SETTLEMENT	PHILOSOPHY	_TRANSPORTATION
V-1700-1799		ENGINEERING	MUSIC	THEATER
_1600-1699	_ARCHITECTURE	EDUCATION	MILITARY	_SOCIAL/HUMANITARIAI
_1500-1599	AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE
_1400-1499	_ARCHEOLOGY-HISTORIC	CONSERVATION	_LAW	SCIENCE
PREHISTORIC	_ARCHEOLOGY-PREHISTORIC	_COMMUNITY PLANNING	_LANDSCAPE ARCHITECTURE	RELIGION
PERIOD	AF	REAS OF SIGNIFICANCE CH	ECK AND JUSTIFY BELOW	

STATEMENT OF SIGNIFICANCE

The Evan Dorsey House is believed to have been built in the late eighteenth century by Evan Dorsey who inherited the Drummine tract of 668 acres from his father Captain Judge Basil Dorsey.

The tract was originally patented by William Cummings in 1746 according to research done by H.H. Hopkins.

By 1858 the mill and millers house was acquired by William Hobbs, the owner of Hobbs Mill (Avignon) on Old Annapolis Road.

The mill continued to operated until 1889 when a flood on the Linganore Creek left the building inoperable.

In 1976, a fire swept through the existing millers house and the structure has deteriarated to ruins since that time.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

GEOGR	APHICAL DAT	TA.	
	F NOMINATED PROPERTY		
	£ 2	- L	on I a man or "Type Fo
VERBAL B	OUNDARY DESCRIPTIO	N .	11 FT.1 W2
LIST	ALL STATES AND COUL	NTIES FOR PROPERTIES OVERLAP	PING STATE OR COUNTY BOUNDARIES
LIST	ALL STATES AND COU	NTIES FOR PROPERTIES OVERLAP	PING STATE OR COUNTY BOUNDARIES
	ALL STATES AND COU		PING STATE OR COUNTY BOUNDARIES
STATE	PREPARED BY	COUNTY	PING STATE OR COUNTY BOUNDARIES
STATE	PREPARED BY	COUNTY	PING STATE OR COUNTY BOUNDARIES
STATE STATE FORM	PREPARED BY Cherilyn Widell	COUNTY	1978
STATE STATE FORM I	PREPARED BY Cherilyn Widell Frederick Count	COUNTY COUNTY , Sites Analyst	1978 Servation DATE 694-1063

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.


The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.


RETURN TO: Maryland Historical Trust

The Shaw House, 21 State Circle

Annapolis, Maryland 21401

(301) 267-1438







NEW MARKET

(GAS HOUSE PIKE- NEW LONDON.)

Photos: LAKIN

EVAN DORSEY MILLERS HSE LAKIN/1973 N/3 GAS HOUSE PILCE NEW LONDON F-5-30 BOUTH ELEVATION



EVAN DORSEY MULIERS HSE CEW 11/17 F-5-30 N/S GAS HOUSE PICE NEW LONDON South ELEVATION



EVAN DORSEP MILLERS HSE

N/S GAS HOUSE PICK NEW LONDON

CEW 9/78

SOUTH BLEVATION

F-5-30